



Replacement Parts for BD Alaris Pumps



**We Repair
PCA Handsets!**

All parts listed below are manufactured by AIV Inc.

With same-day shipping on our AIV manufactured Alaris parts and fast turnarounds on repairs, AIV has what you need to keep your Alaris pumps running.

Part Description	AIV Part #	OEM Ref. #
LVP 8100BD Door Latch Assembly	AL13849	49000441
LVP 8100BD Door Assembly Kit	AL13837	49000438
LVP 8100BD Rear Case Assembly	AL13856	49000436/49000501
POC 8015 M2 Front Case Assembly w/ Keypad	AL13843	TC10012515/TC10013664
POC 8015 M2 Keypad	AL13845	N/A
Flat Rate Repair For 8100BD LVP	FLRT8100BD	N/A
Fixed Rate Repair For 8100BD LVP (parts extra)	RP8100BD	N/A
Fixed Rate Repair For BD Alaris 8015 M2 (parts extra)	RPMEDLEYBD	N/A
PCA Handset Repair	REP148349000	N/A
Alaris-Compatible Power Cord	PC10775	148452-000

877.266.6897 aiv-inc.com



FM 86787