



Baxter® PCA II

Pump Support Program and Parts

Baxter® PCA II



These PCA II replacement parts are manufactured new and are not used, refurbished, or recertified - a truly valuable alternative to new OEM parts.

Description	OEM Part Number	AIV Part Number
Front Housing Assembly	6464940RP	BX12139
Rear Housing Assembly	6464939RP	BX12140
Syringe Cover Assembly	6464611RP	BX12141
Locking Pole Mount Clamp	2L3211	BX12142
Battery Door	6464943RP	BX12143
Keypad	6464195	BX12215
AC Adapter	6464813, 2L3255	ACPCAII
Baxter® PCA II Repair Services		
PCA II Repair	N/A	RPPCAII
PCA II Flat Rate Repair (includes Parts & Labor)	N/A	FLRTPCAII

**Call us today 800.990.2911
or visit us at www.aiv-inc.com**

The manufacturers listed are the holders of their respective names and/or trademarks, and are not to be taken as an endorsement or affiliation with AIV, Inc.

Specialized Repair Services
Accessories
Parts

- Fetal Monitoring
- Pulse Oximetry
- Cardiac Monitoring
- Infusion Therapy

AIV, Inc.
7485 Shipley Avenue
Harmans, MD 21077 USA
p 410.787.1300
f 410.787.1337